

**LANCASHIRE TESTING SERVICES LIMITED**

Lyon Road Industrial Estate : Kearsley : Bolton

Lancashire : BL4 8NB

Tel: +44 (0) 1204 792858

Email: enquiries@ltslab.co.uk

www.ltslab.co.uk

9630

TEST CERTIFICATE

CLIENT:	Interfabrics S.L Pol Ind Francisco Vitoria Calle Del Textil S/N 03830 Muro De Alcoy Alicante, Espana 0	Certificate Number:	UK2000513 -3
		Date Received:	29/06/2020
		Date Issued:	03/07/2020
		Issue Number:	2
		Changes made from previous issue (if applicable)	
		Fabric Composition changed from 100% PES	
Contact:	Toni Fernandez		
Tel:	+34 637494453		
Email:	ajfernandez@aquaclean.com		

SAMPLE IDENTIFICATION

The information in this section is provided by the client and Lancashire Testing Services Ltd assumes no responsibility or liability for its accuracy.

Sample Name / Reference	Energy-FR
Additional Names:	-
Batch Ref/Number:	-
Order Number:	-
Colour:	-
Fabric Composition:	92% PES, 8% PA
Customer:	-

SPECIFICATION

Schedule 4 part I & 5 part I of the Furniture & Furnishings (Fire)(Safety) Regulations 1988 (as amended 1989,1993 and 2010)

TEST METHOD

Flammability:	BS5852:- Part 1:1979:Smouldering Cigarette Source Part 1:1979: Butane Flame Ignition Source 1
Pre-treatment:	BS5651:1978: Clause 4 Water soak, as amended by the Furniture & Furnishings (Fire)(Safety) Regulations 1988 (as amended 1989, 1993, 2010)

Conclusion

The sample tested: **Complies** with the flammability requirements of:
BS5852:Pt1:1979 cigarette source and butane ignition source 1 in accordance with the modifications stated in Schedule 4 part I & Schedule 5 part I of the Furniture & Furnishings (Fire)(Safety) Regulations 1988 (as amended 1989,1993 and 2010), taking into account uncertainty of measurement.

Comments:

**LANCASHIRE TESTING SERVICES LIMITED**

Lyon Road Industrial Estate : Kearsley : Bolton

Lancashire : BL4 8NB

Tel: +44 (0) 1204 792858

Email: enquiries@ltslab.co.uk

www.ltslab.co.uk

9630

TEST CERTIFICATE**Test Results:-****BS5852:Part1:1979: Smouldering Cigarette Source and Butane Flame Ignition Source 1****Ignitability by smokers' materials of upholstered composites for seating**

"The following test results relate only to the ignitability of the combination of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use."

Sample Code			UK2000513 -3						
Sample Name / Reference			Energy-FR						
Client			Interfabrics S.L						
Date of test			03/07/2020						
Pre-Treatment			BS5651:1978: Clause 4 Water soak, as amended by the Furniture & Furnishings (Fire)(Safety) Regulations 1988 (as amended 1989, 1993, 2010) Line Dried during day at ambient temperature						
Filling Type			Carpenter/RP21130 unmodified polyurethane foam of density 20-22Kg/m ³ /Type B, 130						
Size of test rig			Small: Back - 450 x 300 ± 2mm + Seat - 450 x 150 ± 2mm						
Test Conditions			Period h	Temperature °C		Relative humidity %		Air Flow m/s	Volume m ³
Conditioning of test specimens			≥16	15-25		50±20		≤0.2	-
Testing conditions			-	15-30		20-70		0.03	≥6
Testing Source			Smouldering Cigarette Source						
Testing time limit			60 minutes after placement of smouldering cigarette.						
Test No.	Position	Ignition/Non Ignition	Duration of: (min.sec)			Time for: (sec)			
			Ignition Source	Flames	Smoke	Ignition of Test	Cover Splitting	Extinction	
1	LHS	NI	13.51	-	15.08	-	-	-	
2	M	NI	14.06	-	15.34	-	-	-	
Testing Source			Butane Flame Ignition Source 1						
Testing time limit			2 minutes after removal of burner tube (120 seconds)						
Test No.	Position	Ignition/Non Ignition	Duration of: (sec)			Time for: (sec)			
			Ignition Source	Flames	Smoke	Ignition of Test pieces	Cover Splitting	Extinction	
1	M	NI	20	23	37	-	-	-	
2	RHS	NI	20	21	37	-	-	-	
RESULT:			SMOULDERING CIGARETTE SOURCE						PASS
			BUTANE FLAME IGNITION SOURCE 1						PASS
KEY: I = Ignition, NI = Non Ignition, LHS = Left hand side, M = Middle, RHS = Right hand side									

On behalf of Lancashire Testing Services :

 Tony Alcock,
Laboratory Technician:

 John Marsh,
Laboratory Technician:

 Peter Collings,
Operations Manager:

Please note that copies of this original certificate are not valid

Issue Number: 2